

## Determination of residual energy content of high-voltage battery

VIN	TMBJB7NY1NF021790	Model year	2022 (N)
Manufacturer	Skoda	Version	SUV
Model	Enyaq 2021 >, Elroq 2025 >	Engine	Motor

(Confidentiality level: confidential)



## Batterie Health Quicktest

Date:	10.06.2026
Time:	16:11:23
First registration:	OCT 28, 21
Mileage:	214175 km
License plate number:	307KDX
Battery serial number:	288 VWARMIA246
Battery energy content when new in kWh:	58

Residual energy content in % *	<b>72</b>
Qualified measuring value available:	<b>No</b>

### Charged energy\*\*

Total energy charged:	66394.62 kWh
Charged DC energy:	29118.87 kWh
Share of charged DC energy:	43.86 %

### \* Information on the measurement

The measured battery capacity is determined during vehicle operation and is subject to influences of the operating conditions. The result of the measurement may deviate by up to +/- 10 percentage points from the actual energy content.

The residual energy content is measured in the vehicle as a charge quantity in ampere hours (Ah). The usable energy content of the battery in kilowatt hours (kWh) is primarily determined by this residual energy content, and to a lesser extent by driving style, ambient and battery temperature, and the exact state of charge of the fully charged battery.

### \*\* Information about the charged energy

The total charged energy is the accumulated electrical energy that has been charged during the service life.

A small share of DC charging is advantageous for a long battery life.

### Note on new vehicle warranty of ŠKODA AUTO a.s

This battery health status does not in any way establish, limit or extend any existing guarantee claims against ŠKODA AUTO a.s.

Place, Date


Authorized Dealer Signature

10 Jun 2026, 16:11:26

ODIS

List of event memory entries  
 VIN: TMBJB7NY1NF021790  
 Manufacturer: Skoda  
 Model: Enyaq 2021 >, Elroq 2025 >  
 (Confidentiality level: confidential)

Model year: 2022 (N)  
 Version: SUV  
 Engine: Motor




Engine electronics (0001 - Engine electronics for electric powertrain) (0EA906012CL 2219 E-Vehicle 0EA907425C H01)
- 22008 U023500 Lost Communication With Cruise Control Front Distance Range Sensor (00100111 active/static)
23039 U041500 Invalid Data Received From Anti-Lock Brake System (ABS) Control Module "A" (10100111 active/static)
- 31949 U122900 Front camera for driver assistance systems implausible (00100111 active/static)
33295 U041300 Invalid Data Received From Battery Energy Control Module "B" (10100111 active/static)
Electric drive (Electric drive) (1EA907121AC 6044 MEB INV4.0 1EA907121C H09)
- 41735 U112300 Data bus error value received (00100111 active/static)
Passenger's door electronics (Door electronics, front passenger side) (1EB959592A 0641 TSG BFS 1EB959592 003)
196660 B148754 Window regulator motor no basic setting (00001001 active/static)
Brake electronics (0003 - Brake Electronics) (1EA614517AN 0514 ESC-ZF_EBC470 1EA614517 H15)
69648 U164C00 Distance Regulation Control Module No communication (00101111 active/static)
73856 C052800 Steering Angle Sensor Module Range/Performance (00100111 active/static)
Application server 1 system 1 adaptive (Applikationsserver 1 System 1 Adaptive) (V04007003BE 0261 ICAS1 Sys_Ada NULL NULL)
- 8495361 P1CB500 Plug and charge Communication error while installing a vehicle certificate (00101111 active/static)

List of event memory entries

VIN: TMBJB7NY1NF021790  
 Manufacturer: Skoda  
 Model: Enyaq 2021 >, Elroq 2025 >  
 (Confidentiality level: confidential)

Model year: 2022 (N)  
 Version: SUV  
 Engine: Motor




Power steering (Power steering) (1EA907144AG 5024 BASGEN1MQB37 1EA907144H 246)
- 5423 B1168F2 Steering angle sensor no initialization (10100111 active/static)
- 6160 U112100 Data bus missing message (00100111 active/static)
Airbag (15 - Airbag ) (1EA959655CE 0366 VW40Airbag 1EA959655CE 010)
9440027 B100B1B Driver thorax airbag igniter Resistance too high (10101111 active/static)
9873435 B16A81B Igniter for interaction airbag 2nd row, driver side Resistance too high (10101111 active/static)
10026259 B18FD13 Driver side seat occupant detection sensor Open circuit (10101111 active/static)
Emergency call module and communication unit (0075 - Emergency call module and communication unit (OCU 4)) (10A035284D 0486 OCUGen4 10A035284 H17)
- 12866049 U112300 Data bus error value received (00101111 active/static)
Front sensor for driver assistance systems (Front sensor system for driver assistance systems) (1EA980654B 5308 MEB MFK 4.1 1EA980654 H03)
- 1124449 U112100 Data bus missing message (00101111 active/static)
- 1124450 U112100 Data bus missing message (00101111 active/static)
- 1124451 U112100 Data bus missing message (00101111 active/static)

List of event memory entries

VIN: TMBJB7NY1NF021790  
 Manufacturer: Skoda  
 Model: Enyaq 2021 >, Elroq 2025 >  
 (Confidentiality level: confidential)

Model year: 2022 (N)  
 Version: SUV  
 Engine: Motor




- 1124452 U112100 Data bus missing message (00101111 active/static)
- 1124453 U112100 Data bus missing message (00101111 active/static)
- 1124454 U112100 Data bus missing message (00101111 active/static)
- 1124482 U112100 Data bus missing message (00101111 active/static)
- 1124485 U112100 Data bus missing message (00101111 active/static)
- 1124498 U112100 Data bus missing message (00101111 active/static)
1126424 B200FF2 Internal malfunction (00101110 passive/sporadic)
Parking aid (0076 - Parking Aid) (1EA919294D 0421 PDC08K 1EA919294 H02)
1113107 B10FC13 Front parking aid sensor Open circuit (00101111 active/static)
- 13637426 U112300 Data bus error value received (00101111 active/static)
- 13639955 U112300 Data bus error value received (00101111 active/static)
- 13639956 U112300 Data bus error value received (00101111 active/static)

List of event memory entries

VIN: TMBJB7NY1NF021790  
 Manufacturer: Skoda  
 Model: Enyaq 2021 >, Elroq 2025 >  
 (Confidentiality level: confidential)

Model year: 2022 (N)  
 Version: SUV  
 Engine: Motor




- 13639974 U112300 Data bus error value received (00101111 active/static)
- 13647898 U112300 Data bus error value received (00101111 active/static)
Light control left 2 (D6 - Light control left 2) (992941591CD 9102 LED1L 992941591C H08)
139523 C119913 Hi beam light bulb Open circuit (10101111 active/static)
HVAC electronics (0008 - Air conditioner/heater electronics) (1EA907727T 0425 Climatronic 1EA907727R H01)
394240 P123D00 A/C Pressure/Temperature Sensor 1 Pressure lower limit not reached (00100111 active/static)
394246 P123F00 A/C Pressure/Temperature Sensor 2 Pressure lower limit not reached (00100111 active/static)
394257 P124F00 A/C Pressure/Temperature Sensor 3 Pressure lower limit not reached (00100111 active/static)
458499 P1C7E00 A/C Pressure/Temperature Sensor 4 Pressure lower limit not reached (00100111 active/static)
458503 P1C8000 A/C Pressure/Temperature Sensor 5 Pressure lower limit not reached (00100111 active/static)
- 523548 U12DB00 Engine/Motor Control Module received malfunction value (00100111 active/static)
Electronic central electric (09 - Electronic central electronics - ATA) (1EA937089N 0278 SAM_H 1EA937089A H22)
526606 B200009 Control module faulty Component malfunction (00101111 active/static)

List of event memory entries

VIN: TMBJB7NY1NF021790  
 Manufacturer: Skoda  
 Model: Enyaq 2021 >, Elroq 2025 >  
 (Confidentiality level: confidential)

Model year: 2022 (N)  
 Version: SUV  
 Engine: Motor




- 1074823 U112100 Data bus missing message (00100111 active/static)
Data Bus OBD Interface (Data Bus OBD Interface) (1EA937012H 0261 ICAS1 Host-SG 1EA937012A 065)
- 90638 U112300 Data bus error value received (00100111 active/static)
1049251 U122E00 Ethernet databus branch 3 no communication (00100111 active/static)
2232407 U023500 Lost Communication With Cruise Control Front Distance Range Sensor (00100111 active/static)
2232425 U104C00 Rearview camera system control module no communication (00100111 active/static)
2240769 U159800 Burglary protection control module 1 front left no communication (00100111 active/static)
2240770 U159900 Burglary protection control module 2 front right no communication (00100111 active/static)
2494551 U163C00 Ethernet control module, Adaptive Cruise Control no communication (00100111 active/static)
8397571 B1802F1 NV-Energy management Alarm triggered (00100111 active/static)
- 8472065 U112100 Data bus missing message (00100111 active/static)
8491266 U14FE00 Secure onboard communication Signature inspection failed (00100111. active/static)

List of event memory entries

VIN: TMBJB7NY1NF021790  
 Manufacturer: Skoda  
 Model: Enyaq 2021 >, Elroq 2025 >  
 (Confidentiality level: confidential)

Model year: 2022 (N)  
 Version: SUV  
 Engine: Motor



- 8511745 U173E00 Occupant detection Function restriction due to implausible message (00100111 active/static)
- 8540417 U15FA00 EgoMaster Input data error (00100111 active/static)
Hybrid battery management (008C - Battery regulation control module) (0Z1915184J 1041 J840 K8C BMC 0Z1915184D 007)
42275 P0D0F00 Battery Charging System Negative Contactor Stuck Closed (10101111 active/static)
Display unit Driver display (Driver display unit) (5LA920320A 0531 FAHRERDISPLAY 5LA920320 021)
- 16776976 U112100 Data bus missing message (00001001 active/static)